

# Product Safety Recall

## Honda—Honda Rotary Tiller - FG110K1AT & FG110K1UT

*PRA number:* 2016/15358

*Date published:* 5<sup>th</sup> May 2016

### Product information

#### Product description

A Honda powered, walk behind Rotary Tiller

#### Identifying features

FG110K1AT - FAAA-1379577 - 1379793

FG110K1AT - FAAA-1503769 - 1503912

FG110K1UT - FAAA-1200001 - 1540356

#### What are the defects?

During packaging the control cables may have become "kinked" due to crimping. As a consequence, the controls can bind and stick and the tiller tines may begin spinning as soon as the engine is started, or may not be able to turned off.

#### What are the hazards?

If the defect occurs, this may pose a laceration hazard to consumers.

#### Where the product was sold

- Nationally

#### Traders who sold this product

Authorised Honda Power Equipment Dealers

#### Supplier

Honda America Power equipment & Thai Honda Power equipment

#### Supplier's web site

<http://www.honda.com>

#### What should consumers do?

Consumers can contact their local Honda Power Equipment Dealer and arrange to have the unit inspected and, if necessary, repaired at the earliest possible opportunity.

